

Comment Set 35, cont.

Ms. Judy Brown

9

August 13, 2003

pipe placement well below the scour line. However, it has been DFG's experience that the presences of pipes, and the need to maintain cover over those pipes, have created obstacles to dredging or other streambed maintenance activities within some channels. For this measure to be feasible, pipe placement should be at a depth that would not preclude dredging or other streambed maintenance activities, rather than relying solely on the existing scour line.

35-13

General Comments:

- All work proposed within Suisun Marsh must adhere to the October through April closure.
- An easement must be obtained from DFG for two DFG wildlife areas south of Gold Hills Road and east of Highway 680.
- An easement must be obtained from DFG to cross the Yolo Bypass Wildlife Area.

35-14

35-15

If you have questions regarding our comments, please contact Mr. Eric Tattersall, Environmental Scientist, at (707) 944-5546; or Mr. Scott Wilson, Habitat Conservation Supervisor, at (707) 944-5584.

cc: See next page

Comment Set 35, cont.

Ms. Judy Brown

10

August 13, 2003

cc: State Clearinghouse
Post Office Box 3044
Sacramento, CA 95812-3044

Jeff Stuart
National Marine Fisheries Service
650 Capitol Mall
Suite 8-300
Sacramento, CA 95814-4706

Cecilia Brown
U. S. Fish and Wildlife Service
2800 Cottage Way, W2605
Sacramento, CA 95825

Priya Ganguli
Regional Water Quality Control Board
1515 Clay Street, Suite 1400
Oakland, CA 94612

David Cornman
Kinder Morgan
1100 Town & Country Road
Orange, CA 92868

Steve Leach
URS Corporation
500 12th Street, Suite 200
Oakland, CA 94607-4014

Eric Gillies
California State Lands Commission
100 Howe Avenue, Suite 100-South
Sacramento CA 95825-8202

Molly Martindale
U. S. Army Corps of Engineers
333 Market St 8th floor
San Francisco, CA 94105-2197